

I. GENERAL INFORMATION

Service Performed:	Pre-shipment Inspection
Client:	/
Supplier:	Zhejiang Bode Industrial Co.,Ltd
Factory:	Zhejiang Bode Industrial Co.,Ltd
Product Name:	Vehicle
P.O. No.:	/
Item No.:	MC-455
Destination Country:	/
Inspection Date:	26 July 2014
Inspection Location:	Jinhua City, Zhejiang Province, China
Reference Sample:	None







II. INSPECTION SUMMARY





	Passed	Failed	Pending	N/A
A. Quantity		✓		
B. Workmanship				✓
C. On-Site Tests			✓	
D. Product Specification			✓	
E. Packing			✓	
F. Marking & Labeling			✓	
G. Client Special Requirement				✓

Workmanship Summary					
Inspection Standard:	ANSI/ASQ Z1.4-2008		Critical	Major	Minor
Sampling Plan:	Normal, Single	AQL:	Not Allowed	-	-
Inspection Level:	Fixed Sample Size	Accepted:	0	-	-
Order Quantity:	1	Found:	0	0	0
Available Quantity:	0 (0%)	Result:	Not Applicable		
Sample Size:	1 PC				

III. REMARKS

Problem Remarks:	
1.	The quantity check was failed because production was not finished as required. The product was not complete finished, there was no windshield, winch, roof light, alloy and spare tyre were available on site.
2.	There was no complete finished product was available on site. The factory provided the same model engine to do the function check.
3.	The factory could not provide the equipment for displacement test.
4.	The actual test Max speed was 129 km/h, but it stated on client's Spec. was 85 km/h. Please refer to below photos and Section C for details.
5.	There was no complete finished product was available for dry weight check.
6.	No packing material was provided by factory on site.
7.	Some Chinese marking was found on label of cooling component. Please refer to below photos for details.
8.	The marking on front tires and rear tires were not conformed to the client's Spec. Please refer to below photos for details.
General Remarks:	

9.	The scratched mark and dirty mark was found on site, the factory claimed that would be repair and clean before packing. Please refer to below photos for details.
10.	The factory was requested to repair/mend/replace the defective products our inspector found during the inspection.
Factory Information:	
11.	Factory cooperation: <input type="checkbox"/> Good - Enough manpower to assist, and good cooperation. <input checked="" type="checkbox"/> AVERAGE - Enough manpower to assist. <input type="checkbox"/> Poor - Manpower, equipment or document not provided timely.
12.	Number of workers in factory: <input type="checkbox"/> Less than 50 people, <input type="checkbox"/> 50-100 people, <input checked="" type="checkbox"/> 100-500 people , <input type="checkbox"/> 500-1000 people, <input type="checkbox"/> More than 1000 people.
13.	Inspector's opinion on the factory: <input type="checkbox"/> Good - The factory was neat and tidy. The testing equipment was well maintained and calibrated. <input checked="" type="checkbox"/> AVERAGE - The factory was tidy, and the testing equipment ran normally. <input type="checkbox"/> Poor - The factory was messed, the basic testing equipment was not available / not workable.
Sample Collection Record:	
14.	No sample was collected on site.
Photos:	
	
Remark 4: the actual test Max speed was 129km/h	Remark 4: the client's Spec.
	
Remark 7: some Chinese marking was found on label of cooling component	Remark 7: some Chinese marking was found on label of cooling component

	
<p>Remark 8: the actual marking on front tires</p>	<p>Remark 8: the actual marking on rear tires</p>
<p>9)Front Suspension Double A-arm independent 10)Rear Suspension Double A-arm indepe 11)Front/Rear Brakes Dual hydraulic disc 12)Parking Brake Hand-Actuated 13)Front Tires / Model ATV 27 x 8 - 14 14)Rear Tires / Model ATV 27 x 11 - 14 15)Wheels Aluminium 16)Wheelbase (mm/in) 2180 / 85.8 17)Dry Weight(kg/lbs) 530 / 1168.7 18)Overall Vehicle Size (LxWxH) (mm/in) 2</p>	
<p>Remark 8: the client's Spec.</p>	<p>Remark 9: the scratched mark was found on site, the factory claimed that would be repair and clean before packing</p>
	<p>Nil</p>
<p>Remark 9: the dirty mark was found on site, the factory claimed that would be repair and clean before packing</p>	<p>Nil</p>

IV. CONCLUSION

FAILED

PASSED - Conform to Client's Requirement
PENDING - Subject to Client's Evaluation
FAILED - Not Conform to Client's Requirement

Approved by : _____

Note: 1. This report reflects our findings at the time and the place of inspection based on random samples selected. 2. This inspection was carried out to the best of our knowledge and abilities, and our responsibility is limited to the exercise of reasonable one. 3. This report does not relieve the sellers from their contractual obligations nor does it prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our inspection or occurring thereafter. 4. This report does not evidence shipment. 5. Our services are subject to the General Conditions of Service of V-Trust, which is shown at our website and can be sent to you upon written request. 6. This report's inspection results only relate to the samples as (randomly picked) by our inspector. 7. This report is complete and its content may not be reproduced.

Please find our inspection details from next page (Section A – F).

A. QUANTITY

Quantity								Unit: PCS	
P.O.	Item	Order Qty	Qty / Carton	Order Cartons	Quantity Breakdown			Sample Size	
					Packed	Unpacked	Unfinished	Packed	Unfinished
/	MC-455	1	1	1	0	0	1	0	1
Total:		1	-	1	0	0	1	0	1
Selected Cartons :									
1 Carton was selected randomly on site.									
Carton No.:		MC-455	/	/	/	/	/	/	/
Result: Failed									
Remark:		The production was not 100% finished as required.							

B. WORKMANSHIP

Inspection Standard:	ANSI/ASQ Z1.4-2008	AQL	Accepted	Total Found	Result	
Sampling Plan:	Normal, Single	Critical: Not Allowed	0	0	Passed	
Inspection Level:	Fixed Sample Size	Major: -	-	0	Passed	
Sample Size:	1 PC	Minor: -	-	0	Passed	
Workmanship Defectives / Function Inspection Findings						
Description				Critical	Major	Minor
For Item MC-455		Sample size: 1 PC				
1.	No defect was found					
Total found:				0	0	0
Accepted:				0	-	-
Sample size:				1	1	1
Result:	N/A	No client spec., actual finding & record.				
Remark:						
Note: A Defective is defined as a unit of product that contains one or more defects. A Defect is defined as any non-conformance of the inspected unit of product with specified requirements. A single defect is taken into account per each defective unit; only one most serious defect is taken into account per each defective unit.						

C. ON-SITE TESTS

	Description	Method	Sample Size	Result / Reading
1	Function check	As claim on gift box, instruction manual and must conform to indicated function	1pc	Pending
2	All accessories check	Based on parts list on instruction sheet, no missing.	1pc	Pending
3	Fatigue test	for all adjustable parts if applicable, 20 times	1pc	Passed
4	Smell checking	should be as the client requirement	1pc	Passed
5	Rub check	Rub for 15s by cloth with water	1pc	Passed
6	Tape check on silk-screen/painting/electroplate	Use 3M tape for coating, electroplate and printing (logo, rating label and so on)	1pc	Passed
7	Assembly check	Follow product instruction and ease for assembly	1pc	Pending
8	Max speed check	Test by factory equipment (client's 85km/h)	1pc	Pending 129km/h
9	Speed accuracy check	Test by factory equipment, setting 40km/h for factory test method	1pc	Passed 38km/h
10	Brake function test	Test by factory equipment	1pc	Actual finding Left: 679/right: 822
11	Front axle weight test	Test by factory equipment	1pc	Actual finding: Front left: 155kg, front right: 151kg Rear left: 166kg, rear right: 204kg
12	Sideslip test	Test by factory equipment (running 100m, tolerance $\pm 5\%$ for factory test method)	1pc	Passed 0.5m
13	Lamp brightness test	Test by factory equipment	1pc	Actual finding 24778cd
14	displacement test	1100CC	0	Pending
Result: Pending				
Remark:				

*Refer to V-Trust Work Instruction: VTR-WI-CZ-0001.

D. PRODUCT SPECIFICATION

	Client's Spec.	Ref. Sample	1# Sample	2# Sample	3# Sample
Item No.:	MC-455				
L×W×H (mm)	2900x1600x1500	/	2950x1600x1520	/	/
Wheelbase length (mm)	2180	/	2180	/	/
Ground Clearance (mm)	320	/	320	/	/
Fuel Capacity (L)	35	/	35	/	/
Dry Weight (kg)	530	/	/	/	/
Result: Pending					
Remark:					

E. PACKING

Package Details								
Item No.	Qty / Carton		Carton Size L×W×H (cm)		Gross Weight (KG)		Qty / Inner box	
	Marking	Actual	Marking	Actual	Marking	Actual	Marking	Actual



MC-455	/	/	/	/	/	/	/	/
Export Carton Details								
Fastening Metal Staples	/	Nylon Band			/			
Material	/	Corrugated Paper Plies			/			
Packing Method								
No packed good was available on site.								
Assortment Method								
No assortment								
Result: Pending								
Remark:								

F. MARKING & LABELING		
Barcode/Labeling/Printing		
Name	Location	Result
Warning marking	Unit	Pending
Marking	Tires	Pending
Instruction manual and documentation check	Provided By	
No instruction manual included	/	N/A
Shipping Marks		
Shipping Marks (on / side)	N/A	
Side Marks (on / side)	N/A	
Inner Box Marks (on / side)	N/A	
Result: Pending		
Remark:		

G. CLIENT SPECIAL REQUIREMENT		
	Client Requirements	Result
1.	Nil	N/A
Result: N/A No client special requirement.		
Remark:		

H. PHOTOS	
1	Photos of item MC-455



Vehicle view



Front of vehicle



Water-cooled




Car light



Car light



Connector




Winch assembled position



Side of vehicle



Front tires



Marking on front tires




Marking on front tires



Marking on front tires



Marking on front tires



Marking on front tires



Marking on front tires



Marking on front tires



Wheel hub



Details



Inflation



Foot rest




Guard



Warning label



Rear tires



Marking on rear tires



Marking on rear tires




Marking on rear tires



Marking on rear tires



Marking on rear tires



Marking on rear tires



Marking on rear tires



Marking on rear tires



Wheel hub



Details



Inflation



Guard



Warning label



Back of vehicle



Car light



Car light



Car light



Connector



Connector



Side of vehicle



Guard



Warning label



Guard



Warning label




Interior



Interior



Brake



Accelerator



Circuit




circuit



Steering wheel



Operating lever



Handbrake



Display




Cigarette lighter



Cigarette lighter



Warning tip button



Key



Key



Starting lock



Operating button



Drive system




Water-cooled



Warning label



QC passed label



Battery



ECU



Warning label



Warning label



Engine



Rack



Fuel tank



Engine



Marking



Marking



Four-cylinder



Serial No.



Marking



Serial No.



Engine



Engine



Top of vehicle



Cover



Details



Rack




Wheelbase



Overall size check



Overall size check



Overall size check



Overall size check



Function check



Function check



Function check



Function check



Function check



Max speed check



Max speed check shown on display



Max speed check shown on factory test equipment



Speed accuracy check shown on display



Speed accuracy check shown on factory test equipment



Max speed check & Speed accuracy check test equipment



Max speed check & Speed accuracy check test equipment model



Brake function check



Brake function check shown on factory test equipment



Brake function check test equipment



Brake function check test equipment model



Front axle weight test



Front axle weight shown on factory test equipment



Rear axle weight shown on factory test equipment



Axle weight test equipment



Axle weight test equipment model



Sideslip test



Sideslip test shown on factory test equipment



Sideslip test equipment



Sideslip test equipment model



Lamp brightness test

	<p>Nil</p>
<p>Lamp brightness test shown on factory test equipment</p>	<p>Nil</p>

This is The End of the Report

Note: 1. This report reflects our findings at the time and the place of inspection based on random samples selected. 2. This inspection was carried out to the best of our knowledge and abilities, and our responsibility is limited to the exercise of reasonable one. 3. This report does not relieve the sellers from their contractual obligations nor does it prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our inspection or occurring thereafter. 4. This report does not evidence shipment. 5. Our services are subject to the General Conditions of Service of V-Trust, which is shown at our website and can be sent to you upon written request. 6. This report's inspection results only relate to the samples as (randomly picked) by our inspector. 7. This report is complete and its content may not be reproduced.